

Welding Certificate

GSIHal-EN1090-3.00204.2014.004

in accordance with EN 1090-1, table B.1, its hereby declared:
The manufacturer has produced evidence that he fulfills the requirements of the European standard EN 1090-3 for execution of structural aluminium components

Manufacturer	Mansfeld Anlagenbau und Umwelttechnik AG Hübitz Industriechaussee 1 06347 Gerbstedt GERMANY	
Technical specification	EN 1090-3:2019	
Execution class(es)	EXC3 according to EN 1090-3	
Welding Process(es) <small>(Reference no. acc. to DIN EN ISO 4063)</small>	131, 141	
Material Group	22, 23 according to CEN ISO/TR 15608 and EN 1090-3 (2019), table 1 and 2	
Responsible Welding Coordinator <small>(Title, Surname, Name, Qualification, Date of birth)</small>	Bernd Bornack, IWE	born on: 17.06.1956
Substitute <small>(Title, Surname, Name, Qualification, Date of birth)</small>	-	
Confirmation	All provisions concerning welding as described in the above mentioned technical specification(s) were applied.	
Validity start	10.07.2021	
Period of validity	09.07.2024	
Remarks	-	

Place and date of issue Halle (Saale), 15.07.2021
Dr. Kranz/Grunewald




Grunewald
deputy head of test body

Certificate number: GSIHal-EN1090-3.00204.2014.004

General Terms

1. This certificate is valid as long as the terms of the above technical specifications themselves or the manufacturing conditions of the essential manufacturing factory have not changed significantly.
2. This certificate may only be reproduced or published for advertising or other purposes than as a whole. The text of promotional material doesn't has to be in conflict with this certificate.
3. In case of any doubt as to the suitability of the manufacturing factory(ies) there is the possibility reserved by the inspection authority to carry out an unexpected spot checks in the manufacturing factory paid by the manufacturer
4. This certificate may be withdrawn at any time with immediate effect and be amended or modified if the conditions under which it was granted have changed, or if the terms of this certificate are not met.
5. The following changes must be reported to the inspection authority:
 - a) New production or significant changes to essential manufacturing facilities;
 - b) Change of the welding coordinator;
 - c) inception of new welding processes, new base materials and related WPQRs (welding procedure qualification record)
 - d) new essential manufacturing facilities

The inspection authority will cause a supplementary examination in the cases cited

6. At least two months before the expiry date there shall be submitted an application to the inspection authority, when the qualification should be recertified.

distributor

1. Applicant
2. File

